




Fig. 12 The Number of Customers in Okushiri island

affected by the Earthquake




Fig. 14 Distributions of P-wave and S-wave Velocities

with Depth of the Ground

N-value(Large Penetration Tests)




Fig. 13 Permanent Ground Displacement of

Nakanosawa Elementary School




Photo 1 Overall View of the Damage of Aonae District
(Destroyed Tunami and Fire)




Photo 2 Broken Breakwater due to Tsunami at Okushiri island




Photo 3 Broken Embankment due to Tsunami at Taisei-cho