




Before Earthquake



After Earthquake

Photo 4 Collapse of the Slope at Okushiri island




Photo 5 Large Deep Sliding at the Back of The Okushiri-port