



Photo 6 Built-up the Oil pit due to Liquefaction




Photo 7 Built up the Agricultural culvert due to Liquefaction




Photo 8 Overview of the Liquefaction of the Ground of Nakanosawa Elementary School




Photo 9 Damage of Road due to Liquefaction